



# Tech Info Library

## Macintosh 128K, 512K, Plus: ID = 02 Errors From External Drive

Revised: 1/30/92  
Security: Everyone

Macintosh 128K, 512K, Plus: ID = 02 Errors From External Drive

=====

Article Created: 24 October 1985  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

PROBLEM DESCRIPTION: Using external drive on left side of Macintosh gets 02 errors.

CAUSE: Drive could be getting RFI interference from power/sweep PCB inside of Mac.

CURE: Use the external drive on the right side of the Mac. If problem still not saved, search on Macintosh General Troubleshooting.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1412