



# Tech Info Library

## Macintosh 128K, 512K, Plus: Distorted Video/Scorched Components

Revised: 7/17/92  
Security: Everyone

Macintosh 128K, 512K, Plus: Distorted Video/Scorched Components

=====

Article Created: 24 October 1985  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

PROBLEM DESCRIPTION: Left side of Video display stretched with vertical line overlapped. Also often very discolored L2 and/or C2 on power/sweep PCB.

CAUSE: Possible blown flyback circuitry on power/sweep PCB.

CURE: Replace power/sweep PCB. If problem still not found, search on Macintosh General Troubleshooting.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1413