



# Tech Info Library

## Apple IIe: Locks Up With Extended 80 Column Card in AppleWorks

Revised: 1/30/92  
Security: Everyone

Apple IIe: Locks Up With Extended 80 Column Card in AppleWorks

=====

Article Created: 19 December 1985  
Article Last Reviewed: 17 July 1992  
Article Last Updated:

PROBLEM DESCRIPTION: The computer may work fine in other applications but fails with AppleWorks using the extended 80 column card.

CAUSE: The MMU (P/N 344-0010) chip may have failed.

CURE: Replace the MMU or logic board if MMU not available.

If this cure does not resolve the problem, go back to the Word Search screen and search on the product's name and HTS and GTS to obtain a General Troubleshooting procedure.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1600