



Tech Info Library

Apple IIfc Monitors : Wavy Video Display

Revised: 9/29/90
Security: Everyone

Apple IIfc Monitors : Wavy Video Display

=====

Article Created: 19 December 1985
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Video display exhibits a "waving" or
"rippling" effect.

CAUSE: Stand alone power supply manufactured prior to 4584 (i.e.
the 45th week of 1984).

CURE: Check the stand alone power supply date code. If
manufactured prior to 4584, exchange the power supply.

This repair is eligible for warranty coverage to those customers who have
purchased AppleCare for their system. For all others the repair cost
responsibility lies with the customer.

If this cure does not resolve the problem, go to the Tech Procedures
to obtain a General Troubleshooting procedure.

Copyright 1990 Apple Computer, Inc.

Tech Info Library Article Number:1607