



Tech Info Library

Apple III : Won't Boot AII Disk Calibrate in AII Emulation

Revised: 1/17/92
Security: Everyone

Apple III : Won't Boot AII Disk Calibrate in AII Emulation

=====

Article Created: 11 March 1986
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Apple II Disk Calibration Program will not boot on the Apple III in Apple II Emulation mode.

CAUSE: Peripheral cards may be interfering with the Apple II Disk Calibration program.

CURE: Power down the Apple III and remove ALL interface cards, (especially the ProFile interface card). Reboot the Apple II Emulation Disk then load and run the Apple II Disk Calibration Program.

If this cure does not resolve the problem, go back to the Word Search screen and search on the product's name and HTS and GTS to obtain a General Troubleshooting procedure.

Copyright 1988, Apple Computer, Inc.

Tech Info Library Article Number:1817