

ImageWriter 8 And 15 Problem/Cure: Erratic Carrier Motion

Revised: 11/10/88 Security: Everyone

ImageWriter 8 And 15 Problem/Cure: Erratic Carrier Motion

This article last reviewed: 10 March 1988

PROBLEM DESCRIPTION: During printouts, the carrier makes a clattering noise and letters are printed over each other.

CAUSE: The pitch and the character size may not be properly specified in the software causing the carrier assembly to run into the left margin sensor. The carrier reaches the left margin, but in attempting to follow software controls, continues printing on the same line.

CURE: 1. Verify that the software being used is correctly set, for example, 80 characters with 10 pitch, etc.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number: 1823