

Apple IIc Owner's Manual 030-1030-B: Erratum on PR#7 feature

Revised: 1/28/87 Security: Everyone

Apple IIc Owner's Manual 030-1030-B: Erratum on PR#7 feature

Received with the new Apple IIc, the manual with part number 030-1030-B shows, at the top of page 100, how to boot the computer off the external drive as part of a troubleshooting procedure.

However, the manual doesn't state that the PR#7 feature has been removed since the introduction of the UniDisk 3.5 option for the IIc.

Apple Technical Communications

Tech Info Library Article Number:2124