

## SIMMs: Some Are For 68030-Based Systems Only

Revised: 5/27/92 Security: Everyone

SIMMs: Some Are For 68030-Based Systems Only

\_\_\_\_\_\_

Article created: 2 March 1989 Article last reviewed: 20 May 1992

Article last updated:

Some of the SIMMs that are used in the Macintosh IIx will not work in other systems (Macintosh II, Macintosh SE, etc). They have "030 ONLY" stamped on the back.

They don't work in other Macintosh systems because the CAS/RAS signals are reversed (timing-related) from previous SIMMs.

This difference is handled in the Macintosh IIx with additional ROM code. Those SIMMs that are marked for "030 ONLY" will work only in the Macintosh IIx (and any future machines that use the 68030 processor).

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:3538