



# Tech Info Library

## Macintosh II ADB Port: Fuse Specifications

Revised: 7/2/92  
Security: Everyone

Macintosh II ADB Port: Fuse Specifications

=====

Article Created: 21 February 1989  
Article Last Reviewed: 29 June 1992  
Article Last Updated:

TOPIC -----

I think I've blown a fuse on my Macintosh II computer's Apple Desktop Bus (ADB) port. Is this something I can fix?

DISCUSSION -----

The +5-volt line on the Macintosh II ADB port is protected by a subminiature 1-amp, 125VAC, normal-blow fuse. This fuse is soldered to the logic board and is not a user-replaceable part.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:3751