

Macintosh 512K: How to Localize to Spanish

Revised: 6/8/89
Security: Everyone

Macintosh 512K: How to Localize to Spanish

This article last reviewed: 1 May 1989

When trying to localize a Macintosh 512K, some people have reported that the process resulted in the keyboard becoming completely unmapped. That is, keys were interchanged throughout. This can happen when to the standard U.S. Macintosh 512K keyboard (no numeric pad).

The problem results from the U.S. standard keyboard having a different number of keys than the international keyboard. The number of keys affects the mapping. If you are using a Spanish keyboard, select "international keyboard" from the Keyboard CDEV in the Control Panel. Using any Macintosh Plus keyboard also eliminates difficulties.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number: 3920