



Tech Info Library

Internet Router & 6.0.7: Coprocessor not installed error

Revised: 11/6/92
Security: Everyone

Internet Router & 6.0.7: "Coprocessor not installed" error

=====

Article Created: 20 December 1990
Article Last Reviewed: 8 October 1991
Article Last Updated: 8 October 1991

TOPIC -----

I'm having a problem with System Software 6.0.7 and the AppleTalk Internet Router software 2.0. When installed on a Macintosh IIsi with a NuBus Adapter and a TokenTalk card (TokenTalk version 2.0 Arose Prep version 1.1) I receive a system error "Coprocessor not installed". When I install the Internet Router software on a Macintosh IICx, the system does not recognize the router software.

DISCUSSION -----

We tested the same configuration on a Macintosh IIsi acting as a router, and had no trouble installing or running the software.

We've heard complaints about the "Coprocessor not installed" message in varied situations with several different applications. Please see an article titled "Macintosh System Software 6.0.7: Troubleshooting (1 of 3) for more information on this error.

If you can't get the router software to run on the Macintosh IICx, there may be a problem with the way you're installing or configuring it. We recommend you start the installation from scratch using the correct system installer disks to install System software, and the Apple Networks Product installer disk to install the network drivers and the router software. The router should load successfully after re-installation in a clean system.

Copyright 1990, 1991 Apple Computer, Inc.

Tech Info Library Article Number:6538