



Tech Info Library

Macintosh LC and IIsi: No Top Lid Screw in US Models

Revised: 7/17/92
Security: Everyone

Macintosh LC and IIsi: No Top Lid Screw in US Models

=====

Article Created: 1 May 1991
Article Last Reviewed: 17 July 1992
Article Last Updated:

TOPIC -----

Why does Apple ship the Macintosh IIsi and LC without the screw for the top lid?

DISCUSSION -----

The screw is not included on the US version of the Macintosh IIsi and LC because it is not required in the United States.

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:7460