



Tech Info Library

32-Bit Mode: Use SuperClock 3.9.1 for II, IIX, IICX, SE/30 3/93

Revised: 3/2/93
Security: Everyone

32-Bit Mode: Use SuperClock 3.9.1 for II, IIX, IICX, SE/30 3/93

Article Created: 8 October 1991

Article Change History

08/21/92 - RETITLED
 • For clarity; edited.
03/02/93 - REVISED
 • To add 32-Bit System Enabler information.

TOPIC -----

The Macintosh II, IIX, IICX, and SE/30 crash on restart with SuperClock installed and set to 32-bit mode.

DISCUSSION -----

This problem with SuperClock occurs on these Macintosh computers only when they are used in 32-bit mode, such as with A/UX, the 32-Bit System Enabler, or MODE32.

Upgrade to SuperClock 3.9.1 or later, the version that fixes the crash problem in 32-bit mode.

Copyright 1991, 1992, 1993, Apple Computer, Inc.

Tech Info Library Article Number:8935