



Tech Info Library

LC III & LC 575: Use Latest ROMs in Ethernet LC Card (12/94)

Revised: 12/16/94
Security: Everyone

LC III & LC 575: Use Latest ROMs in Ethernet LC Card (12/94)

=====

Article Created: 16 February 1993
Article Reviewed/Updated: 16 December 1994

TOPIC -----

Are there any problems with the Apple Ethernet LC Card (the one requiring the Thin Coax Transceiver) in a Macintosh LC III or LC 575? We're getting a, could not switch to EtherTalk due to an error and that built-in LocalTalk will be used instead, error whenever we switch to Ethernet in the Network Control Panel.

DISCUSSION -----

Be sure your Ethernet LC Card (M0443LL/C or part number 661-0621) has the new ROMs. There was a ROM upgrade for the card, which updated the drivers. Here are the part numbers:

New Apple Ethernet LC Card -----	Old Apple Ethernet LC Card -----
Finished Goods (Assembly)	Finished Goods (Assembly)
P/N: 670-2008	P/N: 670-4443
ROM P/N: 341-0470	ROM P/N: 341-0842

Also, make sure to install the EtherTalk software from the System 7.1 or later disks.

Article Change History:
16 Dec 1994 - Added better description of the Apple Ethernet LC Card.
08 Sep 1994 - Added Macintosh LC 575.

Support Information Services

Copyright 1993-94, Apple Computer, Inc.

Tech Info Library Article Number:11577