



Tech Info Library

System Enabler 111 (1.0.2) Problem (2/93)

Revised: 2/24/93
Security: Everyone

System Enabler 111 (1.0.2) Problem (2/93)

=====

Article Created: 22 February 1993

TOPIC -----

PowerBook 160/180 owners using System Enabler 111 (1.0.2) downloaded from Apple SW Updates on AppleLink, before 02-23-93, experience a crash upon restart if AutoRemounter was installed. The problem was due to the fact that the enabler was corrupted during the posting process.

DISCUSSION -----

Persons who installed System Enabler 111 (1.0.2) from the Express Modem Disk (1.0.1) don't experience the problem.

Solution: The 02-23-93 posting of System Enabler 111 (1.0.2) is OK.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:11619