



# Tech Info Library

## System 7.5: DayStar Accelerator Cards and Mode32 (2/95)

Revised: 2/16/95  
Security: Everyone

System 7.5: DayStar Accelerator Cards and Mode32 (2/95)

Article Created: 19 September 1994  
Article Reviewed/Updated: 16 February 1995

TOPIC -----

Customers with DayStar accelerator cards are reporting problems after installing System 7.5.

DISCUSSION -----

According to DayStar tech support, Mode32 needs to be installed prior to System 7.5 in order to use the PowerCache cards with System 7.5. The PowerCache cards will not work in the Mac II, Mac IIX, or Mac IICX without it. They have been doing in house testing with Mode32 v7.5 and have found no problems.

However, use of MODE32 version 1.2 with System 7.5 may cause serious file corruption. Customers need to get Mode32 v7.5 in order to use both the PowerCache card and System 7.5 on Macintosh computers that do not have 32-bit ROMs.

Article Change History:  
16 Feb 1995 - Reviewed for accuracy and changed keyword.  
08 Nov 1994 - Noted that MODE32 must be installed prior to System 7.5.

Support Information Services

Copyright 1994-95, Apple Computer, Inc

Tech Info Library Article Number:16313