

Color Stylewriter 2400 & ClarisWorks: FPU Not Installed (5/95)

Revised: 5/4/95 Security: Everyone

Color Stylewriter 2400 & ClarisWorks: FPU Not Installed (5/95)

Article Created: 23 January 1995 Article Reviewed/Updated: 4 May 1995

TOPIC -----

I get an error message that says, "Floating Point Coprocessor Not Installed" when I launch the database function of ClarisWorks.

I have a Performa 636CD, System 7.5, and ClarisWorks 2.x. The Color StyleWriter 2400 driver is selected in the Chooser.

DISCUSSION -----

We were able to duplicate your problem with Clarisworks 2.x. When we installed ClarisWorks 3.0 the problem was resolved. To solve this problem, you have two options available:

- 1) You can contact Claris for a maintenance upgrade of 2.1 (2.1.4 is the version you need).
- 2) You can contact Claris for a upgrade to version 3.0 of ClarisWorks.

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor for additional information.

To locate a vendor's address and phone number, use the vendor name as a search string.

Article Change History: 04 May 1995 - Added information on 2.1.4 upgrade.

Support Information Services

 $.. TIL 17057- Color_Stylewriter_2400_ and_Claris Works-FPU_Not_Installed_5-95_ (TA 33187). pdf$

Copyright 1995, Apple Computer, Inc.

Tech Info Library Article Number:17057