



Tech Info Library

DECK II and Power Macintosh 7xxx computers (5/96)

Revised: 5/21/96
Security: Everyone

DECK II and Power Macintosh 7xxx computers (5/96)

=====

Article Created: 21 May 1996

TOPIC -----

This article describes an issue with the applicatin DECK II by Macromedia on some Power Macintosh 7xxx computers.

DISCUSSION -----

Macromedia has confirmed a problem with DECK II, a digital multi-track audio recording application, on some Power Macintosh 7200, 7500, and possibly 7600 computers.

The symptom is after recording a sound the audio tracks will not be in synchronizion. The audio tracks can be shifted manually to put them back in synchronization.

The issue occurs with any version of DECK II up to version 2.5.1. It occurs with either the 1/8" sound input jack or the RCA input jack. They have confirmed some Power Macintosh 7xxx computers do not exhibit this symptom.

Macromedia is investigating this problem and plans to have a resolution in a future software update of DECK II.

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:19832