Tech Info Library

LaserWriter Pro 630: No difference in ROM revisions (7/94)

```
Revised:        7/5/94
Security:       Everyone
```

LaserWriter Pro 630: No difference in ROM revisions (7/94)

===

Article Created: 5 July 1994

TOPIC ---

I had my LaserWriter Pro 630 repaired and the motherboard was replaced. The new
motherboard has v2.0 ROMs, whereas my original had v1.0 ROMs. I think the new
ROMs have changed the serial settings at switch positions 0 and 2. Does this new
set of ROMs change the settings?

DISCUSSION --

At switch position 0 and 2, both sets of ROMs configure the serial port as
documented in the manual:

```
Switch Position 0      1.0 ROMs            2.0 ROMs
                       --------            --------
                       PostScript          PostScript
                       RS-232              RS-232
                       9600 Baud           9600 Baud


Switch Position 2      1.0 ROMs            2.0 ROMs
                       --------            ---------
                       PostScript          PostScript
                       RS-232              RS-232
                       19200 Baud          19200 Baud
```

Support Information Services

Copyright 1994, Apple Computer, Inc

Tech Info Library Article Number:15743