Tech Info Library

Apple Telecom 2.0 and Earlier: PCI Bus Power Mac Issue (5/96).

```
Revised:        5/23/96
Security:       Everyone
```

Apple Telecom 2.0 and Earlier: PCI Bus Power Mac Issue (5/96).

```
=====================================================================
```

Article Created: 28 June 1995
Article Reviewed/Updated: 23 May 1996

TOPIC --

This article discusses compatibility issue between PCI bus Macintosh computers
(like the Power Macintosh 9500) and Apple Telecom software.

DISCUSSION ---

Power Macintosh computers that ship with the PCI bus are not compatible with
Apple Telecom 2.0 or earlier versions when used with a GeoPort Telecom Adapter.
Users should upgrade to Apple Telecom 2.1 or later software.

If you are using a GeoPort Telecom Adapter on these Power Macintosh models, you
must disable LocalTalk. To do this, disconnect any LocalTalk devices attached to
the printer port (serial devices can remain attached).

Article Change History:
23 May 1996 - Updated for technical accuracy.

Copyright 1995-96, Apple Computer, Inc.

Tech Info Library Article Number:18049