Tech Info Library

Apple IIGS: RAMDisk Hides Second 3.5 Drive from Pascal 1.3

```
Revised:        5/25/89
Security:       Everyone
```

Apple IIGS: RAMDisk Hides Second 3.5" Drive from Pascal 1.3

===

This article last reviewed: 3 September 1987

When using Pascal 1.3 on an Apple IIGS with two 3.5" drives and a RAMDisk
active, the second 3.5" drive can't be accessed. Here's why: using the
RAMDisk causes the Apple IIGS SmartPort firmware to move the second drive to
slot 2, drive 1. Because Pascal doesn't use this slot as a storage device,
you can't access it there.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:524