Tech Info Library

Enhanced IIe: What to do When Interrupts Don't Work (10/94)

```
Revised:        10/18/94
Security:       Everyone
```

Enhanced IIe: What to do When Interrupts Don't Work (10/94)

===

Article Created: 22 July 1985
Article Reviewed/Updated: 18 October 1994

TOPIC ---

I notice that interrupts no longer function on my Enhanced IIe, is there a
workaround?

DISCUSSION --

Interrupts pass through the 80-column firmware in the Enhanced IIe, and so
interrupts will not work if you have no 80-column card installed. There are
three ways to solve the problem:

1. Install an 80 column-card
2. Make sure your disk contains ProDOS 1.1.1
3. If neither of the above solutions seem to work, use the BASIC command
   POKE 49162,0 to fool your IIe into thinking that it contains an
   80-column card.

Article Change History:
18 Oct 1994 - Reviewed for technical accuracy, revised formatting.

Support Information Services

Copyright 1985-94, Apple Computer, Inc.

Tech Info Library Article Number:1227