Tech Info Library

Hard Disk 20 P/C: First Time Start-Up = Init Failed

```
Revised:        1/30/92
Security:       Everyone
```

Hard Disk 20 P/C: First Time Start-Up = "Init Failed"

===

This article last reviewed: 29 April 1988

PROBLEM DESCRIPTION: When initializing a Hard Disk 20 with a
known good Mac, the Mac displays an "Init Failed" message.

CAUSE: The HD 20 may have a failed Controller PCB.

CURE: Replace the modules in this order:

        1. Controller PCB
        2. Analog PCB/HDA Module

If this cure does not resolve the problem, go to the Technical Procedures
to obtain a General Troubleshooting procedure.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1604