# Tech Info Library

## MacX & MacTCP: unimplemented co-routine error 12 (11/94)

```
Revised:        11/7/94
Security:       Everyone
```

MacX & MacTCP: "unimplemented co-routine error 12" (11/94)

=====================================================================

Article Created: 5 November 1990
Article Reviewed/Updated: 07 November 1994

TOPIC -------------------------------------------------------

I am running a Macintosh Portable with MacTCP and MacX.  When starting up MacX,
I get the error message "unimplemented co-routine error 12." I get the same
error message when I try to use NCSA Telnet without MacTCP. The same
configuration worked on other Macintoshes.

Do you know of any problems using these two software components on a Macintosh
Portable?

DISCUSSION --------------------------------------------------

The problem may be improper installation of CommToolbox, MacTCP, and/or MacX. We
tested both MacX and NCSA Telnet 2.3 on a Macintosh Portable and didn't have any
problem.  Here are some things to check:

- Make sure that the CommToolbox is properly installed and that the
  "Communications Folder" folder was created in the "System Folder".

- Make sure that the "MacTCP" and "AdminTCP" CDEVs are in "System Folder"
  and that the "MacTCP Tool" comm tool is in the "Communications Folder"
  folder.

- Make sure that all MacX fonts are installed in the "MacX Fonts" folder.

- Make sure that MacTCP is properly configured on the network.


Article Change History:
07 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Tech Info Library Article Number:6361