Tech Info Library

MacX25: Problems Using with Macintosh IIsi

```
Revised:        4/20/93
Security:       Everyone
```

MacX25: Problems Using with Macintosh IIsi

```
=====================================================================
```

Article Created: 23 March 1991

```
Article Change History
----------------------
04/20/93 - REVIEWED
              • For technical accuracy.
```

TOPIC ---

I installed MacX25 on a Macintosh IIsi and then tried to start the MacX25
Admin program. The MacX25 Admin program doesn't recognize my AppleSerial
NB Card: I keep getting a "Status" "Out of service" message.

Is this a known problem?

DISCUSSION --

You are mostly likely using the first version of MacX25; the MacX25 server
and MacX25 Admin software version 1.0 doesn't work on any computer that
requires System Software 6.0.7 (such as the Macintosh IIsi). The problem
involves the "Gestalt" function and is fixed in version 1.0.1 of MacX25.

Version 1.0.1 of MacX25 is compatible with both System 6.0.7 and System 7.
To use the MacX25 server software under System 6.0.7, you'll need at least
2MB of RAM. Under System 7, you'll need at least 4MB of RAM.

Copyright 1991-93 Apple Computer, Inc.

Tech Info Library Article Number:7239