Tech Info Library

Solana H Server: Problems with Large Phase 2 Networks

```
Revised:         4/10/92
Security:        Everyone
```

Solana H Server: Problems with Large Phase 2 Networks

===

Article Created: 17 March 1991
Article Last Reviewed: 10 April 1992
Article Last Updated: 10 April 1992

TOPIC ---

Is there a problem using Solana H-Servers on large multiple-zone AppleTalk
Phase 2 networks?

DISCUSSION --

There is a problem maintaining router tables on very large networks.

Occasionally, several routers can get their battery-backed RAM blown,
though they still stay running from 30 minutes to several hours, depending
on network traffic. When the routers finally start to go down, you'll begin
to see erroneous, duplicated, and scrambled zone names and device names.
Then all the routers will stop completely and begin flashing their error
indicators.

You can restart the routers, but their routing tables will be scrambled.
Each time you try restarting the problem only gets worse. Completely
resetting PRAM only temporarily fixes the problem.

Solana has discontinued business to our knowledge, so we are unable to
refer you to them directly for further information.

Copyright 1991, 1992 Apple Computer, Inc.

Tech Info Library Article Number:7271