Tech Info Library

Macintosh SE/30: Video Flashes are Normal

```
Revised:        7/2/91
Security:       Everyone


Macintosh SE/30: Video Flashes are Normal


======================================================================



Article Created: 5 April 1991
Article Last Reviewed:
Article Last Updated:

TOPIC -----------------------------------------------------------

The video display of my Macintosh SE/30 has horizontal lines flashing from
left to right.  Is this normal?

DISCUSSION ------------------------------------------------------

Up to a point, this is a normal part of the Macintosh SE/30's video
display.  If the flashing is very noticeable you might want to have the
analog board or the video board checked out.  Also, you might try turning
the brightness down a bit.

Copyright 1991, Apple Computer, Inc.


Tech Info Library Article Number:7835
```