Tech Info Library

System 7: 64K Buffer RAM on Farallon Card for AppleShare Server

```
Revised:        12/8/92
Security:       Everyone


System 7: 64K Buffer RAM on Farallon Card for AppleShare Server


=====================================================================


Article Created: 7 December 1992



TOPIC -------------------------------------------------------------


My AppleShare server is responding very slowly since installing the
Farallon Ethernet card.  It's a System 7 compatible card and has
System 7 compatible driver software.  I sometimes experience
temporary network disconnects.



DISCUSSION --------------------------------------------------------


Farallon Ethernet-equipped Macintosh computers that get heavy network
traffic like AppleShare file servers require additional buffer RAM on
the Farallon Ethernet card.  Most Farallon Ethernet cards ship with
16K of buffer RAM.  But 64K is recommended if the network traffic
is high.  You can obtain the additional RAM from Farallon.

To locate a vendor's address and phone numbers, use the vendor name as a
search string.

Copyright 1992, Apple Computer, Inc.


Tech Info Library Article Number:10978
```