Tech Info Library

32-Bit System Enabler: DayStar Compatibility (3/93)

```
Revised:        3/23/93
Security:       Everyone
```

32-Bit System Enabler: DayStar Compatibility (3/93)

===

Article Created: 23 March 1993

TOPIC --

I installed the 32-Bit System Enabler on a Macintosh IIcx with a DayStar
accelerator. When I restart and check the Memory control panel, 32-Bit
addressing is turned on. But when I select "About This Macintosh..." the
system software is taking all memory above 8MB just as it does when 24-Bit
addressing is used.

DISCUSSION ---

DayStar Digital Technical Support indicates that both the PowerCard series
and PowerCache series products work properly with the 32-Bit System
Enabler. They did indicate that in one instance during testing they had to
reset the PRAM before the 32-Bit System Enabler would work with a
PowerCache card.

Please contact DayStar Digital directly. DayStar Digital Technical Support
is searching for configuration information that would allow them to
reproduce the problem.

To locate a vendor's address and phone numbers, use the vendor name as a
search string.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:11835