Tech Info Library

Video Mirroring and PowerLink Presentor Issue (10/93)

```
Revised:        10/25/93
Security:       Everyone
```

Video Mirroring and PowerLink Presentor Issue (10/93)

==

Article Created: 20 October 1993

TOPIC ---

When I purchased E-Machines' PowerLink Presentor there was a Release Note
document giving me the latest information not covered in the Owner's Guide.
Under Video Mirroring, it stated: "Some user's report problems with Apple's
video mirroring feature with Presentor. The problem is caused by a bug in
Apple's PowerBook Display control panel software. We recommend that you do
not use this feature until you receive updated software from Apple."

Is this a known bug and is Apple sending out new software?

DISCUSSION --

It is reported that E-Machines', a division of SuperMac Technology, latest
software release of PowerLink Presentor version 1.0.2 solves this problem.
We downloaded it from their BBS at 408-541-6190. You can also look on
AmericaOnline and CompuServe.

To locate a E-Machines' address and phone number, use SuperMac Technology
as a search string.

Copyright 1993, Apple Computer, Inc.

Tech Info Library Article Number:13771