Tech Info Library

System 7.5 MUK: GeoPort Update Information Read Me (2/95)

```
Revised:        2/16/95
Security:       Everyone


System 7.5 MUK: GeoPort Update Information Read Me (2/95)


======================================================================

Article Created: 2 September 1994
Article Reviewed/Updated: 16 February 1995


TOPIC -------------------------------------------------------

The following article is the "GeoPort Update Information ReadMe" from the System
7.5 Multi-Pack Upgrade Kit.


DISCUSSION --------------------------------------------------

GeoPort Update Information

Version 1.0.1 of "GeoPort for Power Macintosh" was not available for this
version of the CD.

GeoPort will be updated in it's next release to work with Macintosh System 7.5.
We expect the release to be available by the end of 1994.  Apple apologizes for
any inconvenience this may cause you in the interim.

You may contact the Apple Assistance Center at 1-800-SOS-APPL for ordering
information.

NOTE
----
This is not part of the Read Me file. GeoPort for Power Macintosh 1.0 and 1.0.1
will function with System 7.5, but there are outstanding bugs customers need to
work around:

• 1.0 has two problems with virtual memory:
  - Network file transfers will fail when VM is on.
  - Data connections will fail when VM is on.

• 1.0 and 1.0.1 will crash the computer on restart if there are any Faxes
  waiting to be sent in the Waiting to be Faxed folder.

• The modem speaker must be turned off at all times through the Express
```

Modem control panel to prevent intermittent crashing.

This article can help you locate the GeoPort for Power Macintosh 1.0.2 update, it is available on online services:

- "Where To Find Apple Software Updates"
  Lists online services for "free" Apple software updates.

Article Change History:
16 Feb 1995 - Reviewed for technical accuracy, revised System 7.5 keyword.
05 Oct 1994 - Added NOTE section to article.

Support Information Services

Copyright 1994-95, Apple Computer, Inc

Tech Info Library Article Number:16174