Tech Info Library

AudioVision: System 7.5 Requires AppleVision SW v1.0.1 (1/96)

Revised: 1/25/96
Security: Everyone

AudioVision: System 7.5 Requires AppleVision SW v1.0.1 (1/96)

===

Article Created: 24 April 1995
Article Reviewed/Updated: 25 January 1996

TOPIC ---

I just upgraded from System 7.1 to System 7.5, and noticed that my Sound control
panel no longer shows the AudioVision option. I have reinstalled the AudioVision
software using the Installer disk that originally came with my AudioVision 14
Display, but it did not solve this problem. How can I get the AudioVision option
back?

DISCUSSION --

Neither System 7.5 or System 7.5 Update 1.0 come with the required ~AudioVision
extension you need. The supported display software for your monitor on a System
7.5.x computer is AppleVision Display Software 1.0.1. This software is available
from online services.

These articles can help you locate software updates mentioned here:

• Where To Find Apple Software Updates
  Lists online services for "free" Apple software updates

• Obtaining Apple Product Support in the USA
  Lists 800 numbers and online services for software updates, Apple
  support information, and a subset of the Apple Tech. Info. Library

Article Change History:
25 Jan 1996 - Made title more descriptive.
14 Sep 1995 - Corrected minor typo.
05 Sep 1995 - Added AppleVision Display software information.

Support Information Services

Copyright 1995-96, Apple Computer, Inc.

..TIL17645-AudioVision-System_7-5_Requires_AppleVision_SW_v1-0-1_1-96_(TA33648).pdf

Tech Info Library Article Number:17645