Tech Info Library

Energy Saver 2.0.2: Error Message on Startup (10/96)

```
Revised:        10/14/96
Security:       Everyone
```

Energy Saver 2.0.2: Error Message on Startup (10/96)

==

Article Created: 14 October 1996

TOPIC ---

I performed a clean installation of System 7.5.3 from the Macintosh System 7.5
Version 7.5.3 CD-ROM disc, and then I installed System 7.5.5 Update on my Power
Macintosh 8500. When I restarted the computer, a dialog appeared with this
message, "...the energy saver extension is incompatible with this system. It's
version 2.0.2 but should be version 2.0.2." What is wrong?

DISCUSSION --

Make sure you are using the same version of the Energy Saver control panel and
Energy Saver extension. Then, increase the memory partition of the Energy Saver
control panel by 23K to correct this.

Copyright 1996, Apple Computer, Inc.

Tech Info Library Article Number:20527