



# Tech Info Library

## Apple IIe Hardware: Reference Manual Errata

Revised: 9/21/84  
Security: Everyone

Apple IIe Hardware: Reference Manual Errata

=====

Page 133 in Chapter 6: Switching I/O Memory, Table 6-5

### READS:

|            |                        |        |       |        |       |
|------------|------------------------|--------|-------|--------|-------|
| SLOT CXROM | Slot ROM at \$3x00     | \$C007 | 49159 | -16377 | Write |
|            | Internal ROM at \$Cx00 | \$C006 | 49158 | -16378 | Write |

### SHOULD READ:

|            |                        |        |       |        |       |
|------------|------------------------|--------|-------|--------|-------|
| SLOT CXROM | Slot ROM at \$3x00     | \$C006 | 49158 | -16378 | Write |
|            | Internal ROM at \$Cx00 | \$C007 | 49159 | -16377 | Write |

Apple Technical Communications

Tech Info Library Article Number:164