



Tech Info Library

Softcard III: Problems using .RS232, .PRINTER and CP/M

Revised: 11/30/84
Security: Everyone

Softcard III: Problems using .RS232, .PRINTER and CP/M

=====

Both the .RS232 and .PRINTER drivers were designed to use the built in serial port (Port C) on the Apple III. If one configures the CP/M system such that both of these drivers are active and assigned to logical devices, the first attempt to send or receive characters causes the system to crash with an inverse S D (System Death) displayed on the console. Reboot your system to recover.

Apple Tech Notes

Tech Info Library Article Number:616