



Tech Info Library

Apple IIC (platinum): Mouse Moved from Slot 4 to Slot 7

Revised: 10/12/87
Security: Everyone

Apple IIC (platinum): Mouse Moved from Slot 4 to Slot 7

=====

This article last reviewed: 28 September 1987

When the latest ("platinum") version of the Apple IIC was released, the main circuit board was changed to accommodate the new Memory Expansion Card. The firmware was also changed: the logical location for the mouse was moved from slot 4 (where the memory card image now resides) to slot 7.

This causes problems when customers run the sample BASIC program in Appendix A of the AppleMouse II User's Manual. To make the program work correctly with the newest Apple IIC, change all occurrences of [slot] 4 to [slot] 7.

Tech Info Library Article Number:790