



Tech Info Library

Macintosh : Bomb and ID=02 Errors On Older Macintosh

Revised: 7/17/92
Security: Everyone

Macintosh : Bomb and ID=02 Errors On Older Macintosh

=====

Article Created: 24 October 1985
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Getting random "Bomb and ID=02" errors on the Macintosh.

CAUSE: Static charge on the old type of CRT is arcing, causing errors.

CURE: Locate the band holding the CRT to the front of the Macintosh. If the band has black tape around it, then it is the old CRT and this fix could work. If an old CRT, put the electrical insulating washers between the front of the Macintosh and each screw holding the CRT band. If the problem still is not saved, search on "Macintosh General Troubleshooting" for additional information.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1414