



Tech Info Library

ImageWriter II: SheetFeeder Causes Top/Bottom Margin Problems

Revised: 11/10/88
Security: Everyone

ImageWriter II: SheetFeeder Causes Top/Bottom Margin Problems

=====

This article last reviewed: 10 March 1988

PROBLEM DESCRIPTION: The ImageWriter II SheetFeeder pulls the paper in about a 1/4" too much. The end result is a document that has a 1.25" margin at the top and a .25" margin at the bottom.

CAUSE: DIP switch set incorrectly

CURE: 1. Switch 5 on the ImageWriter II should be set to open.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1826