



Tech Info Library

LaserShare 1.0: Error Can Result From Changing Long Spooler Name

Revised: 11/2/88
Security: Everyone

LaserShare 1.0: Error Can Result From Changing Long Spooler Name

=====

This article last reviewed: 7 January 1988

A system error can occur on LaserShare 1.0 when a very long spooler name is changed.

If the user has a multi-zone network, with multiple LaserWriters in each zone, when starting LaserShare and capturing the printer, LaserShare will show a system error (ID=02) when the user tries to alter the default spooler name provided in the dialog box.

In this example:

Zone name = INFO. SERVICES

Laser name = LASERWRITER PLUS- SOUTH

the generated name is

LASERWRITER PLUS- SOUTH INFO. SERVICES...SPOOLER (48 characters)

which runs out the end of the text box. If the user tries to type a shorter name, LaserShare crashes.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:1860