



# Tech Info Library

## Macintosh Plus P/C: No Response From Apple Personal Modem

Revised: 1/17/92  
Security: Everyone

Macintosh Plus P/C: No Response From Apple Personal Modem

=====

This article last reviewed: 10 March 1988

PROBLEM DESCRIPTION: When using the old MacTerminal program with the Macintosh Plus and the Apple Personal Modem, there is no response from the modem.

CAUSE: The Data Terminal Ready (DTR) signal is not activated from the old serial driver. This signal would normally be used by the Macintosh to let the modem know that it is activated. Without DTR the modem will not look at any other signals from the Macintosh.

CURE: Use MacTerminal 2.0 with the new system and finder because it will activate the DTR signal on the Macintosh Plus.

If the above cure doesn't fix the problem, refer to the Tech Procedures for this product's troubleshooting procedure.

Copyright 1988, Apple Computer, Inc.

Tech Info Library Article Number:1884