



# Tech Info Library

## Macintosh SE: Video Problems

Revised: 1/17/92  
Security: Everyone

Macintosh SE: Video Problems

=====

Article Created: 31 July 1987  
Article Last Reviewed: 17 July 1992  
Article Last Updated: 17 July 1992

BEFORE YOU START: Familiarize yourself with the Macintosh SE Technical Procedures. Be sure to follow proper ESD procedures.

PROBLEM DESCRIPTION: The Macintosh SE video screen slowly fades until there is no visible display at all.

PROBLEM CURE: Replace the Video Board, part number 661-0372 (or update to new part number). The video board is located on the back of the CRT assembly.

The video Board provides video amplification and over-voltage protection to the video circuit.

Copyright 1987, 1988, 1992 Apple Computer, Inc.

Tech Info Library Article Number:2268