



Tech Info Library

LocalTalk PC Card: Version 2.0 Changes

Revised: 11/2/88
Security: Everyone

LocalTalk PC Card: Version 2.0 Changes

=====

This article last reviewed: 30 March 1988

Version 2.0 of the LocalTalk PC Card driver (ATALK.EXE) does not use the card's hardware interrupt feature. This means that the default card settings do not conflict with a COM2 serial port, and the LocalTalk PC Card can coexist with other devices using hardware interrupts.

Conflicts with other cards are unlikely because the LocalTalk PC Card driver uses relatively little used address spaces and M60 software interrupts.

No changes were made to the LocalTalk PC Card driver with respect to the DMA channels or card address range. The driver was rewritten and code optimized to take up less space, and a numeration problem was fixed.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:2792