

Apple IIGS: Some Memory Upgrades Have Faulty RAM

Revised: 11/10/88 Security: Everyone

Apple IIGS: Some Memory Upgrades Have Faulty RAM

This article last reviewed: 10 November 1988

There has been a problem with certain RAM chips used in the Apple IIGS RAM expansion card. It is a refresh problem, not a loading problem. One symptom: AppleWorks crashes after being in use for a while.

Service stock has been purged of RAM upgrade kits with suspected bad RAM chips, so any new upgrades should have no problem.

If you suspect bad RAM, check the date codes on the chip. The suspected bad numbers are 8752 and 8801.

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number: 3032