



Tech Info Library

Macintosh IIX: System 6.0.2 And Excel 1.5 Bug Fix

Revised: 5/31/89
Security: Everyone

Macintosh IIX: System 6.0.2 And Excel 1.5 Bug Fix

=====

This article last reviewed: 9 December 1988

Excel 1.5 on a Macintosh IIX running System v6.0.2 currently does not recognize the 68882 coprocessor.

The information returned by the SysEnvirons call has been changed slightly in System 6.0.2, and that is what is causing the problem. (This situation does not occur when using System Software 6.0.)

Microsoft is aware of the problem. Contact them for further information.

(NOTE: The 68882 FPU is a superset of the 68881 FPU, and code written for the 68881 works properly with 68882.)

Copyright 1988 Apple Computer, Inc.

Tech Info Library Article Number:3443