



# Tech Info Library

## **LaserWriter IINT: Not Recognized by Radius Accelerator**

Revised: 3/4/90  
Security: Everyone

LaserWriter IINT: Not Recognized by Radius Accelerator

=====

This article last reviewed: 17 March 1989

When using a Macintosh with the Radius accelerator card, the system fails to recognize the printer on the network, a LaserWriter IINT. This is a problem with the ROMs on the Radius accelerator card. There is no current solution.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:3691