



# Tech Info Library

## HyperCard: Problem With Dial Command and Apple Personal Modems

Revised: 8/23/89  
Security: Everyone

HyperCard: Problem With Dial Command and Apple Personal Modems

=====

This article last reviewed: 17 August 1989

TOPIC -----

Where can I find the documentation for driving (play) telephone tones from HyperCard?

The application that I am working on requires talking to an audio response unit at a bank that automates bill paying. The remote machine talks using digitized audio requesting account code, password, and so on, expecting the user to type in appropriate responses from the telephone keypad. I want to automate this in HyperCard.

My Apple Personal Modem and the dial command appear to have limitations (perhaps just limited documentation) that prevent me from doing what's needed -- namely, to order the modem to dial a number with a ";" appended so that it remains off hook when a voice answers. Instead, the dial command appears to strip off this character.

Can the modem be used this way?

DISCUSSION -----

Certain Apple Personal Modems, those with a serial numbers beginning with a C621301 to C745577, do not work properly with the HyperDialer stack.

The problem exists because one of Apple's vendors incorrectly substituted 2.3-ohm resistors for 4.7-ohm resistors, which altered some characteristics of the modem. The resistors are surface-mount type, numbered R106-107, with the following numbers on the resistors: 4R7 (incorrect) or 2R3 (correct).

Try to dial using a modem outside the range specified above. If the problem is not present in that situation, the original modem can be fixed by any Apple service provider.

Copyright 1989 Apple Computer, Inc.

Tech Info Library Article Number:4239