



Tech Info Library

LapLink III: Macintosh IIfx Compatibility CDEV Available

Revised: 6/29/90
Security: Everyone

LapLink III: Macintosh IIfx Compatibility CDEV Available

=====

This article last reviewed:

TOPIC -----

LapLink III for the Macintosh does not work on the Macintosh IIfx. On launch, it crashes with an ID = 1.

DISCUSSION -----

Traveling Software has heard reports of this problem. They are currently trying to locate the cause. If they find a fix for this situation, we will post the information.

Apple provides a CDEV that turns off the IOP of the Macintosh IIfx. This CDEV is available for licensing from the Software Licensing group. Traveling Software has obtained the license for this CDEV and will be providing it to registered users of LapLink III for the Macintosh. Contact Traveling Software for this CDEV. For more details, search the Technical Info library under "Traveling Software."

Copyright 1990 Apple Computer, Inc.

Tech Info Library Article Number:5665