

Tech Info Library

800K INIT: Use with System 6.0.3 or Earlier

Revised: 4/18/91 Security: Everyone

800K INIT: Use with System 6.0.3 or Earlier

This article last reviewed: 4 June 1990

TOPIC -----

Was the 800K INIT fix included as part of System 6.0.3 (and later) software? Is it part of the System file? I can't find an INIT file called 800K INIT.

DISCUSSION -----

You do not need to use the 800 K INIT with System Software 6.0.4 or later because its equivalent is built in--it's actually part of the System file. However, you do need to install it on Macintosh computers with 800 K drives when using System Software 6.0.3 or earlier.

Copyright 1990 Apple Computer, Inc.

Tech Info Library Article Number: 5712