



Tech Info Library

80MB Hard Drive: External to Internal Conversion

Revised: 4/11/91
Security: Everyone

80MB Hard Drive: External to Internal Conversion

=====

This article last reviewed: 11 October 1990

TOPIC -----

My 80MB external hard drive worked fine upon arrival. However, after I took it out of its case and made it an internal drive, it won't boot.

DISCUSSION -----

The modified drive is probably not terminated automatically. To see if this is the problem, put a SCSI system cable with a SCSI Terminator on the external SCSI port. If it boots with the external terminator, then you need to have the jumpers on the bottom of the drive set to terminate it. Contact your authorized Apple service provider for this.

Copyright 1990 Apple Computer, Inc.

Tech Info Library Article Number:6518