



Tech Info Library

System 7: Upgrades for Apple Product Compatibility

Revised: 5/31/91
Security: Everyone

System 7: Upgrades for Apple Product Compatibility

Article Created: 28 May 1991
Article Last Reviewed:
Article Last Updated:

TOPIC -----

This document lists products on the April 1991 Suggested Retail Price List that require updating and are incompatible with Macintosh System Software version 7.0, or both.

DISCUSSION -----

Apple Products Updated By System 7

The following Apple products require software updates for use with System 7. System 7 software includes the update software. Users should not use the installer disks that come with the product; use the equivalent System 7 software or Custom Install option instead.

| | |
|-----------|--|
| M5540LL/A | Macintosh Portable Backlight Screen Upgrade |
| M0268 | Macintosh Portable Internal 40SC Hard Disk |
| M2620/A | Apple Hard Disk 20SC |
| M2644/A | Apple Hard Disk 40SC |
| M2688/A | Apple Hard Disk 80SC |
| M2666 | Apple Hard Disk 160SC |
| M0216/A | Macintosh Internal 20SC Hard Disk (SE, SE/30, II, IIx or IIfx only) |
| M0283 | Macintosh Internal 40SC Hard Disk (IIcx or IIci only) |
| M0269 | Macintosh Internal 40SC Hard Disk (SE, SE/30, II, IIx or IIfx only) |
| M0284 | Macintosh Internal 80SC Hard Disk (IIcx or IIci only) |
| M0270 | Macintosh Internal 80SC Hard Disk (SE, SE/30, II, IIx or IIfx only) |
| M0267 | Macintosh Internal 160SC Hard Disk (II, IIx or IIfx only) |

| | |
|-----------|--|
| M0235 | Macintosh SE-Bus Drive Card |
| M0234 | Macintosh II PC Drive Card |
| M0410LL/A | Macintosh II EtherTalk® NB Card |
| M0264 | Apple Serial NB Card |
| M0237 | Apple TokenTalk® NB Card |
| M0261/A | Apple Coax/Twinax Card (requires MacDFT or 3rd party equiv.) |
| M0443LL/A | Apple Ethernet LC Card |
| B0438LL/A | StyleWriter Printer w/Acc. Kit & Ink Cartridge |
| C0090LL/A | ImageWriter II Printer |
| A9B0314 | ImageWriter II/LQ LocalTalk Option |
| M6009 | LaserWriter IINT Controller Card |
| M6210 | LaserWriter IINT w/Toner Cartridge and Letter Cassette |
| M6004/A | LaserWriter IINTX Controller Card |
| M0445LL/A | LaserWriter IINTX Upgrade Kit |
| M6215/A | LaserWriter IINTX w/Toner Cartridge and Letter Cassette |
| M0191 | LaserWriter Plus Kit |
| B0454LL/A | Personal LaserWriter LS w/Toner Cartridge & Acc. Kit |
| M0097LL/A | Personal LaserWriter NT Controller Card |
| B0325LL/A | Personal LaserWriter NT w/Toner Cartridge & Letter Cassette |
| B0326LL/A | Personal LaserWriter SC w/Toner Cartridge & Letter Cassette |

Products Requiring Separate Upgrades

The following Apple products require software upgrades that are not included with System 7. See the System 7 Information icon on AppleLink for information on how to acquire the upgraded software.

Upgrades Available Now

| | |
|---------|--|
| M0697 | Inter•Poll Network Administrator's Utility |
| M2700/B | AppleCD SC |
| A9M0337 | Apple Scanner |

Upgrades Available June/July 1991

| | |
|-----------|---------------------------------|
| M6045 | MacTCP |
| M0108LL/B | MacX 1.1 |
| M1043LL/A | MacX 1.1 Update |
| M0695 | MacDFT® |
| B0324LL/B | Apple Coax/Twinax Card w/MacDFT |

Upgrades Available Later in 1991

| | |
|-----------|---------------------------------|
| M0122 | Macintosh Display Card 8•24 GC* |
| M0516LL/A | A/UX Incremental Update Kit |
| M0598LL/A | A/UX 2.0.1 CD-ROM Product |
| M0616LL/A | A/UX 2.0.1 Floppy Product |
| M0559LL/A | A/UX Update Product - CD ROM |

* Hardware is functional but software does not work in accelerated mode.

Incompatible Products

The following product is incompatible with System 7, but can be used with third-party backup software:

M2640/B Apple Tape Backup 40SC

The following systems should not be upgraded to System 7:

B0452LL/A Macintosh IIci A/UX Hard Disk 80 CPU (8MB)
B0452LL/A Macintosh IIci A/UX Hard Disk 80 CPU (8MB)
B0453LL/A Macintosh IIfx A/UX Hard Disk 160 CPU (4MB)
B0453LL/A Macintosh IIfx A/UX Hard Disk 160 CPU (4MB)
B0471LL/A Macintosh IIfx A/UX Hard Disk 160 CPU (8MB)
B0451LL/A Macintosh IIsi A/UX Hard Disk 80 CPU (5MB)

The following products should not be installed on a System 7-based system. Install System Software version 6.0.7 or 6.0.8 before installing these products on a server or router. They are network-compatible with System 7, and both System 6 and System 7 systems can use their services.

M0576 AppleShare Print Server
M0548/B AppleShare File Server 2.0

Copyright 1991, Apple Computer, Inc.

Tech Info Library Article Number:7132